



- 1. ENSURE THAT THE GASKET HOLES ARE ALIGNED WITH THE FLANGE HOLES.
- 2. WITH THE SWIVEL IN THE VERTICAL POSITION, LOWER THE FAST BOLT THROUGH THE FLANGE HOLE. (DETAIL A)
- 3. TURN THE SWIVEL TO THE VERTICAL POSITION. (DETAIL B)
- 4. LOWER THE LEVER DOWN UNTIL SNUG. (DETAIL C)
- 5. WILE THE LEVER RAISED SLIGHTLY FROM THE CLOSED POSITION, TWIST THE SWIVEL CLOCK-WISE, SO THAT A SMALL AMOUNT OF FORCE IS NEEDED TO COMPLETELY CLOSE THE HANDLE. (DETAIL D)
- 6. REPEAT THE ABOVE PROCEDURE UNTIL ALL FAST BOLTS ARE INSTALLED.
- 7. SLIGHTLY RETIGHTEN EACH FAST BOLT SO THAT THEY ALL REQUIRE ROUGHLY THE SAME AMOUNT OF FORCE TO CLOSE HANDLE. TIGHTEN BOLTS IN A CROSSING PATTERN.

\*\*HANDLE SHOULD BE CLOSED BY HAND ONLY\*\*

PAGE 2 OF 2

